

The Sollatek Three Phase Automatic Voltage Regulator (AVR)

Instruction Manual



Issue: July 2021

Important: This manual contains important safety instructions. Keep this manual handy for reference.

Table of Contents

SECT	ION		PAGE
1.	Unpacl	king and Inspection	3
2.	Installa	ation	3
	2.1	Safety	
	2.2	Positioning	
	2.3	Ventilation	
	2.4	Cables and Terminations	
	2.5	Circuit Breakers	
	2.6	Incoming Connections	
	2.7	Outgoing Connections	
3.	Systen	n Power-up	5
4.	Function	onal Description	5
	4.1	General Function	
	4.2	AVR Function	
	4.3	AVS Function	
	4.4	-HA Function	
	4.5	Bypass Function	
	4.6	Surge Arrester	
5.	Maint	enance	8
6.	Trouble	e Shooting	9
	6.1	Safety	
	6.2	False Starting	
	6.3	Shut Down	
	6.4	Common Troubleshooting Points	
	6.5	Error Mode	
7.	Specifi	ication	10
8.	Appen	dix 1: General Arrangement	21
9.	Appen	dix 2: Bypass Installation	22
10.	Appen	dix 3: Circuit topology	24
11.	Appen	dix 4: On-site test procedure	32
		e test/acceptance form	
		e repair and test procedure	
12.	Appen	dix 5: Circuit diagrams	41

Page 2

1. Unpacking and Inspection

It is possible that the unit will have sustained damage during transit. The following procedure should be followed immediately upon receipt of the unit.

- **1.1 Crate/Packaging** Check for transit damage.
- **1.2 Cabinet/Casework** Check for visible signs of damage to exterior panels, doors and fittings. If cracks, scratches or dents are visible there is a chance of internal damage. Particular attention should be paid to the terminal panel.
- **1.3** Internal components Unlock the door using the key provided. Inspect for damage to the transformers, PCBs and other components. All mountings should be tight and there should be no sign of movement of the transformers.
- **1.4 Internal wiring** All wiring connections should be checked to ensure that transit vibration has not loosened screw terminals.

If inspection reveals problems in the above or other areas, the carrier should be notified as soon as possible in writing.

2. Installation

2.1 Safety

Under no circumstances should any work be carried out on the unit unless the supply is isolated.

2.2 Positioning

The unit should be sited indoors on a firm, level, dry surface, away from sources of heat, dust, vibration or moisture. A position allowing access on all four sides to permit preventative maintenance would be advantageous.

2.3 Ventilation

The unit should be positioned such that a free flow of air is available. It is especially important to ensure that cooling fan outlets are free from obstruction. A free space of at least 300mm should be left in all directions around the AVR.

2.4 Cable and terminals

Before any connections can be made the incoming and outgoing cable sizes have to be selected and, on 200A units and above, the appropriate ring terminals fitted. (See Table 2.4.1). Cable size may be selected using values of current given in table 2.4.1 bearing in mind the usual limiting factors such as volt drop, heating, etc. The appropriate breaker sizes are also given. Note that the input and output currents can differ by 40%. This means that a larger cable size may have to be employed on the input than the output.

Output Amps/p		kVA (240V)	Input A (Max)	Input MCCB	Output MCCB	Ring Size mm	
10	7.2	4.2	14	16	10	8	
20	14	8.1	28	32	20	8	
30	21	12	41	50	32	8	
50	36	21	69	80	50	8	
75	54	31	103	100	80	8	
100	72	42	138	160	100	8	
150	108	62	207	200	160	8	
200	144	83	275	320	200	16	
300	216	125	413	400	320	16	
400	288	166	550	630	400	16	
500	360	208	690	800	630	16	
600	431	249	830	1000	630	16	

Table 2.4.1

2.5 Circuit breakers

The recommended input and output breaker ratings are given in table 2.4.1. Values not shown may be interpolated. Due to the fact that breaker ratings jump in large steps it is strongly recommended that adjustable trip level MCCBs are used. In this way a high degree of protection may be achieved. The input MCCB should be of a type suited for use with inductive loads (with a high initial surge current). The output breaker should be chosen to suit the nature of the load.

2.6 Incoming connections

The three incoming lines should be connected to the terminals marked R1 S2 T3 on the terminal panel in the section marked INCOMING MAINS. The incoming neutral is connected to the N terminal and the system earth is connected to the E terminal. N.B. The AVR must be supplied with an incoming neutral which should be fully rated. Care should be taken to ensure that all terminals are securely tightened. See diagram 2.6.1

2.7 Outgoing connections

The three outgoing lines should be connected to the terminals marked R1 S2 T3 on the terminal panel in the section marked OUTGOING MAINS. The outgoing neutral should be connected to the N terminal and the load earth to the E terminal. N.B. All neutrals should be fully rated. Care should be taken to ensure that all terminals are securely tightened. See diagram 2.6.1 Ensure phase rotation continuity from input to output.

INCOMING MAINS

R1 = Phase 1 in

S2 = Phase 2 in

T3 = Phase 3 in

N = Fully rated neutral in

E = Supply earth

OUTGOING MAINS

R1 = Phase 1 out

S2 = Phase 2 out

T3 = Phase 3 out

N = Fully rated neutral out

E = Load Earth

Connections should be made using ring terminals or using the screw terminals provided.
Ensure connections are tight.




Diagram 2.6.1 Terminal Arrangement

3. System power-up

Before the system is powered-up for the first time the following checks should be carried out by qualified personnel only.

Inspect the input and output terminations for tightness, correct wiring and phase rotation.

- 1. Check that the building electrical service is of sufficient capacity to supply the input current of the AVR, remembering that this can be 40% higher than the output current to the load.
- 2. Check building electrical service is of correct nominal voltage and wiring configuration and that main circuit breakers are suitable for the inductive nature of the load represented by the AVR.
- 3. Ensure that the load equipment is ready to be energised. Once the above conditions have been verified, input power may be applied to the AVR. Once input power is applied the three digital voltage meters on the door of the AVR should indicate a valid output voltage. If this is not the case switch off the power immediately and refer to the troubleshooting section of this manual. The AVS indicators on the door (if fitted) should show 'on' (after the wait time of 3 minutes).

Once input power is applied the three digital voltage meters on the door of the AVR should indicate a valid output voltage. If this is not the case switch off the power immediately and refer to the troubleshooting section of this manual. The AVS indicators on the door should show 'on' (after the wait time of 3 minutes). When it has been verified above that the AVR is functioning correctly, the incoming power should be switched off and the output circuit breaker set to the on position. If power is now re-applied, the load will be automatically supplied when the 3 minute delay time has elapsed.

4. Functional Description

4.1 General Function

This three phase AVR is made up from three identical single phase regulator units. Each of these monitors its own output voltage and adjusts for variations in mains supply voltage so as to maintain an output voltage within close limits. When the AVS function is fitted the outputs from the regulators are connected through a contactor to the load. The contactor is controlled by a three phase Automatic Voltage Switcher PCB which monitors the AVR outputs. This connects the load only when all the phase voltages are within acceptable limits. There is a delay between the time when all voltages come within limits and the contactor switching on. This is so as to allow the supply to stabilise and to avoid repeated switching of the load on and off should the mains supply be exceptionally erratic. The state of the AVS circuit is indicated on the front panel by three large LEDs, Green for On, Yellow for Wait and Red for Off.

4.2 AVR Function

This is based on an auto transformer with tap changing on the output. There are seven taps to each transformer giving an accurate output voltage for a wide range of input voltage. The taps are switched by generously rated Triac banks to cope with motor start loads. Low value resistors are fitted with each Triac to ensure that high currents are shared equally between the Triacs within each bank. This technique results in a voltage stabiliser which has no moving parts, responds quickly to voltage fluctuations and is not as large or heavy as other AVRs utilising different regulation techniques.

A micro-controller forms the heart of the control system. It measures the AVR output voltage and turns on the appropriate Triac bank to select the correct tap. A potentiometer is provided for fine adjustment of the output voltage. The micro-controller also measures the frequency of the mains supply and compensates accordingly. This also means that the AVR will work over a frequency range of 45 - 88Hz automatically and down to as low as 30Hz for short periods to help cope with diesel generator loading problems.

Frequency and voltage measurements are filtered by the circuit and software to remove noise and so prevent spurious tap changes.

A watchdog function is implemented in the micro controller. This independently monitors the operation of the micro-controller and its software. If it detects a malfunction, it will reset the micro and re-initialise the control system.

The low voltage DC supply to the control circuit is also protected by a fuse.

Additionally, a hardware reset circuit is included which monitors the supply rail for the control circuit. If the mains is so low that the control circuit will not function correctly, the monitor circuit will put the micro-controller into the reset state and turn off all Triacs.

When the mains supply increases to a usable level, the monitor circuit will restart the micro and the system will re-initialise. This ensures an orderly and controlled restart from a brownout or blackout condition. The circuit is designed with a large hysteresis so that the unit will not attempt to turn on again until the supply voltage is sufficient to withstand possible starting surges. This avoids the possibility of such a surge of current causing the supply to dip sufficiently to turn the unit off again.

Additional protection is provided by temperature sensors fitted to each transformer. If the AVR is used at full load and either the ambient temperature is excessively high or the ventilation grills have been obstructed, the temperature of the transformer may increase beyond reasonable limits. In such an event, the temperature sensor will disconnect the supply to the corresponding control board and thereby turn the output off. When the transformer has cooled sufficiently, the sensor will restart the AVR.

When restarting after the above condition the AVR may cause equipment to begin to operate suddenly. Steps should be taken to ensure that this does not expose persons to risk.

4.3 AVS Function [Optional - has to be ordered separately at time of purchase]

4.3.1 General Description

The Automatic Voltage Switcher (AVS) is a device for the protection of electrical equipment against fluctuations, interruptions and other abnormalities in the electricity mains supply.

The Three Phase AVS monitors various parameters of the mains supply, and keeps it connected to the equipment so long as all the parameters are within defined acceptable limits. This is the normal condition and it is indicated by a Green LED (light emitting diode). If the mains voltage goes outside these limits, the AVS disconnects the equipment from the mains and this is indicated by the Red LED (In some options, it is possible to select indication only without disconnection's.) When the mains supply returns within the acceptable limits, indicated by an Amber LED, the mains remain disconnect from the equipment during the wait time, set to a nominal 1 minute by factory selected components. If during the wait time the mains again goes outside the limits, the wait time starts from the beginning At the end of the wait time, when the mains supply has been continuously within the limits for its duration, normal condition returns indicated by the Green LED, and the equipment is re-connected to the mains.

The parameters monitored by the Three Phase AVS are:

a) Value of the Mains Voltage

The normal condition is when the values of the mains voltage of all the phases are within certain preset limits referred to as the "window". The AVS detects when the voltage of any one or more phases goes outside the window, either over- or undervoltage.

b) Phase Relationship (timing)

The AVS monitors the phase relationship between the three phases of the supply. The normal condition is when the phase difference between the three phases is 120 degrees, corresponding to T/3 where T is the period of one cycle.

c) Phase Rotation [optional]

The AVS can detect a phase rotation error of the three phase mains supply. Detection of parameters c) and d) above is not standard, but are obtained by an optional plug-in board. On this board, it is possible to select by a d.i.l. switch whether abnormality is indicated only, or it causes disconnection also

4.3.2 Principle of Operation

The frequency and phase rotation detection circuits are explained in a separate section. The detailed operation of the AVS in detecting the other parameters is given under CIRCUIT DESCRIPTION below. Basically, however, the AVS compares the peak of the mains AC sinusoid of each phase with two references, one corresponding to the lower or undervoltage limit of the window, and the other to the upper or over-voltage limit. If the mains is normal, so that the peaks lie between the two limits and also within a time not exceeding T/3 (T is the period of one cycle), a monostable is triggered which, after the wait time, switches the power to the equipment. If any one or more of the peaks are below the lower limit, above the upper limit or the separation between two consecutive peaks exceeds T/3, the AVS is reset to disconnect the equipment.

4.3.3 Checks and adjustments

a) Window Limits

P1 and P2 are adjusted to equalise the three phases, so that P1 adjusts the peak at the junction of P1 and R12, and P2 at the junction of P2 and R20 to make them equal to the peak at the junction of R2 and R3. For measurement, an ordinary multi-meter or digital multi-meter may be used on the AC range, since these give readings proportional to peak.

P3 and P4 adjust the limits of the window. Start with these around the centre of their travel. Connect the normal three phase supply to the AVS with one phase via a Variac and monitor voltage with voltmeter. Adjust Variac to the under-voltage limit. Adjust P4 so that indication goes from Red to Amber. Adjust Variac to over-voltage limit. Adjust P3 so that indication fluctuates between Amber and Red.

If the Variac is set so that the voltage is within the window, with Amber indicating, after the wait time (nominal 1 minute) Green will indicate and the contactor is energised.

For a complete check, three Variacs should be used, one on each phase, and the various combinations of under- and over-voltage on each phase with the others tested.

b) Wait Time

The wait time is given by 0.7xR37xC6. With R37 = 820K and C6 = 100uF, the wait time is around 60 sec. to within the tolerance of the components.

4.4 -HA Option

This option is available on all ratings of the AVR (Automatic Voltage Regulator) three phase units larger than 21kVA.

The standard Three Phase AVR provides an output which is stable to within + 4% given an input voltage variation of + 27% from a defined nominal. Although it is likely that voltage stability of + 4% will meet most customers' requirements, higher accuracy can be provided by incorporating a further 'fine' resolution stage beyond the standard AVR system.

The standard AVR incorporates a fully electronic (static) 7-tap changing system providing an output regulated to +4%. This is fed to the -HA option which utilises a further 7 taps, again fully electronic, to achieve an output stability of +2.0%.

4.5 Bypass Option

4.5.1 Manual Bypass

This is used to take the AVR out of circuit, bypassing the supply straight to the load. A fully rated, in line, mechanical switch is used to achieve this, as opposed to a relay or electronically based system. This ensures that the supply to the AVR cannot be re-connected unintentionally by component failure or supply disruptions. This is particularly important if the bypass is used to enable maintenance to be carried out.

4.5.2 Automatic Bypass

This facility operates to bypass the supply directly to the load in the event of a problem associated with the AVR. If the temperature sensors built into the transformers detect that overheating is taking place due to overloading, poor ventilation or high ambient, the bypass operates. Similarly, if the microprocessor detects that a problem has occurred within the AVR itself, the supply is bypassed to the load.

4.6 Surge Arrester

4.6.1 Function

The unit is designed to prevent high voltage spikes and surges from causing damage either to the AVR or to equipment down the line from the AVR. These spikes are commonly caused by lightning, substation load switching or heavy motor load switching.

4.6.2 Operation

The unit is connected in parallel with the supply incoming to the AVR, forming a spur. If built in to the AVR it will be situated above the connection terminals at the rear. Two indicators per phase are provided to give warning of reduced protection level, in order that the surge arrester may be replaced before protection is lost. The unit incorporates multi-stage MOV protection circuits.

5 Maintenance

This is a fully solid state AVR with no moving parts and therefore requires only the minimum of maintenance. You can expect many years of trouble-free service with the AVR completely unattended.

Isolate the incoming mains supply before carrying out any maintenance.

The only maintenance required is to clean any dust and dirt from the outside and inside of the casework which could be restricting the free ventilation of the equipment. If there is a build up of dust on the PCB then this should also be carefully removed with a soft brush. It is also wise on any equipment periodically to check the security of the electrical connections and the condition of the cabling. Again ensure the power is turned off before starting work.

If the AVR is damaged for any reason, or you suspect a fault, contact your nearest Sollatek agent or Sollatek (UK) Ltd Head office for advice.

Sollatek UK Limited

Sollatek (UK) Ltd. Sollatek House, Waterside Drive, Langley, Slough SL3 6EZ UK

Tel: +44 (1753) 214 500 sales@sollatek.com www.sollatek.com

6 Troubleshooting

6.1 Safety

Under no circumstances should any work be carried out on the unit unless the supply is isolated.

6.2 False Starting

If it is found that the AVR keeps trying to start but turns off immediately, this is most likely to be due to poor wiring to the AVR or in the building. This could be:

- 1. Cabling is not thick enough.
- 2. Cabling is too long for its thickness leading to excessive volt drop.
- 3. Poor joints or connections.

Any such problems should be corrected, so that the supply can deliver the high currents necessary to run the load.

6.3 Shut Down

If it is found that the unit switches off after some time even when the mains voltage is good, it may be that the AVS is detecting some bad condition of the mains supply that is not apparent without the use of test equipment.

Alternatively, it may be that the temperature overload is operating, in which case the following points should be checked:

- 1. The output current is not above that stated on the serial label at the rear of the AVR.
- 2. The AVR is not subject to excessive ambient temperature due to a poor location near a source of heat.
- 3. The ventilation grills on the side of the AVR case have not been covered or blocked.
- 4. That there is room for free movement of air around the outside of the AVR casework.

6.4 Common Troubleshooting Points

Problem AVR trips main breaker at switch on.	Cause/Solution1. Check that input and output wiring is not shorted out.2. Check that input circuit breaker is suitable for inductive loads.
AVR shuts down after a period of normal operation. blocked.	 Check that load does not exceed rated output. Check that ventilation ducts/fan outlets are not Incoming voltage may be too low to drive AVR electronic systems.
AVR shuts down immediately upon switch on.	 Check terminal joints and connections satisfactorily made. Check incoming cable is of sufficient capacity. Check that cable run not too long causing excessive volt drop.
Input power is present but there is no output.	 Check that AVS indicators (if fitted) show 'on' Check that circuit breakers (if fitted) are in the 'on' position.
Three phase equipment rotates backwards.	Phase rotation problem. Check incoming and outgoing mains wiring

www.sollatek.com

Error Modes 6.5

If the AVR has shut down it is possible to observe the LEDs on the PCBs within the unit. These can display two different error modes.

This procedure should be carried out by qualified personnel only.

The main door to the unit may be opened whilst the supply is still connected. It is then possible to see the PCBs. There are a number of LEDs visible down one edge of each of the three PCB groups. One of the following two error indications may be observed.

- 1. The square LEDs in a group scan in a cyclical pattern starting at the top moving to the bottom repeatedly. This indicates that a fault has occurred in the voltage measurement feedback circuit. Contact your nearest Sollatek agent or Sollatek (UK) for advice.
- 2. The green and red undervoltage LEDs in the same group flash. This indicates that an AVR system fault has occurred. Again, contact Sollatek for advice.

These indications may be observed on any or all of the three PCB groups.

7. Specifications

Model : Three Phase Automatic Voltage Regulator

Input voltage : 230/400V +22% -30% (Other voltages available)

Output voltage : 230/400V +/- 4% (+/- 2.0% with HA Option)

Correction time : within 15 m sec Frequency range : 45Hz to 88Hz

Voltage protection : Automatic under voltage protection

THD : < 0.25%

Max. amb. Temp.

Acoustic Noise

Expected Service Life : > 25 years

Technology : All solid state (static) switching

: 40 C

: < 45 dB

Bypass modes : Manual bypass for maintenance. Automatic bypass on

(Optional) AVR fault and overload.

Restart modes : Supply to output is automatically disconnected when

(optional AVS) supply outside preset limits and re-connected when

voltage becomes good. Built-in 3 minute delay.

Filtering (Optional) : Input and output noise and spike filtered

Standards : Manufactured to comply with :-

> EN60065 EN60555 BSEN50081 BSEN50082

Sollatek تقسری فیز آٹومیٹک وولٹیج ریگولیٹر (AVR)



جولائی 2021

اہم بات: یہ کتابجہ اہم حف ظمعتی ہدایات پر مشتل ہے۔ رجوع کرنے کے لیے اسس کتابیج کو پاسس رکھیں۔

1. ذبا كھولت اور حبائج پڑتال كرنا

مسکن ہے کہ منتقلی کے دوران یونٹ کو نقصان پہنچ ہو۔ یونٹ موصول ہو حبانے کی صورت میں فوری طور پر مندر حبہ ذیل طسریقہ کار پر عمسل کیا حبانا حیا ہیئے۔

- 1.1 کریٹ اسکینگ منتقلی کے دوران ہونے والے نقصان کی پڑتال کریں۔
- 1.2 سیدن کیس ورک بیرونی پینلز، دروازوں اور تنصیبات پر نقصان کے واضح نشانات کی پڑتال کریں۔ اگر چھٹنے کے نشانات، حسراشیں یا چیکنے کے نشانات واضح ہوں تو اندرونی نقصان کا امکان ہے۔ ٹرمینل کے بینل پر خصوصی توجب دی حبانی حب بینے۔
- ت.1 اثدرونی احب زاء و نسراہم کردہ حبابی کا استعمال کرتے ہوئے دروازہ کھولیں۔ ٹرانسفار مسرز، PCBs اور دیگر احب زاء میں نقصان کی پڑتال کریں۔ تمام ماؤنشگر مضبوط ہونی حبابئیں اور ٹرانسفار مسرز کے بلنے کی کوئی عسلامت دکھائی نہیں دینی حب بیئے۔
- 1.4 اندرونی تاروں کی ترتیب اسس امسر کو یقینی بنانے کے لیے تاروں کے تمسام کنشنز کی پڑتال کی حبانی حب بیئے کہ منتقلی کے دوران ہونے والی بل حبل سے کیلوں کے ٹرمینلز ڈھیلے سے ہو گئے ہوں۔

اگر جبانج پڑتال کے دوران مندر حب بالا یا کسی اور پہلو میں مسائل کا شائب ہو، تو کیریئر کو حبلد از حبلد تحسریری طور پر اطلاع دی حسانی جا بیئے۔

. تنصيب

2.1

یونٹ پر کمی بھی صورت میں کام نہیں کیا حبانا حیا بیئے جب تک سیلائی کو الگ سنہ کر لیا حبائے۔

يوزيثننك

یونٹ عمارت کے اندر ایک ایسے معتام پر لگایا حبانا حب پیئے جس کی سطح مضبوط، ہموار اور ختک ہو اور تپشش، وهول مٹی، بل حبل یا نمی کے ذرائع سے دور ہو۔ ایک ایسی پوزیشن مسائدہ مسند ثابت ہو گی جو کہ حساروں اطسراف سے احتیاطی مسرمت کے لیے رسائی کے مسائل بنائے۔

2 نظام ہواداری

یونٹ کی پوزیشن المبی ہونی حپ بیٹے کہ ہوا کا گزر مسکن ہو۔ اسس امسر کو یقینی بنانا بھی حناص طور پر اہم ہے کہ کولئگ کے چنکھے کی نالیاں رکاوٹ سے پاک ہوں۔ AVR کے گرد ہر سے میں کم از کم 300mm کی حنالی جگہ۔ چھوڑی حبانی حب پیئے۔

2.4 تار اور فرمینگز

کی فتم کے کنیکٹنز فت تم کے حبانے سے قبل آنے اور حبانے والی تار کے سائز منتخب کرنے ہوں گے اور 200A اور زائد کے یو نئس میں منسب چوڑی والے ٹرمینلز نصب کے حبانے حیائیں۔ (2.4.1 حبدول ملاحظہ کریں)۔ تار کا سائز حمد بندی کے عصوی عناصر میں کہ ہینٹک وغیرہ کو ذہن میں رکھتے ہوئے حبدول 2.4.1 میں دی گئی ویلیوز کا استعال کرتے ہوئے منتخب کیا جب سکتا ہے۔ موزوں بریکر سائزز بھی فنداہم کے گئے ہیں۔ یاد رکھیں کہ ان پٹ اور آؤٹ پٹ کرنٹس 40٪ کی شرح سے مختلف ہو سکتی ہیں۔ اسس کا مطلب ہے کہ آؤٹ پٹ کی فبرور سے پڑ سکتی ہے۔

چوڑی سام mm	ئے ہے۔ MCCB	اِن پئر MCCB	اِن پٹ A (زیادہ سے زیادہ)	kVA (240V)	kVA (415V)	نوٹ ئے آ Amps/ph
8	10	16	14	4.2	7.2	10
8	20	32	28	8.1	14	20
8	32	50	41	12	21	30
8	50	80	69	21	36	50
8	80	100	103	31	54	75
8	100	160	138	42	72	100
8	160	200	207	62	108	150
16	200	320	275	83	144	200
16	320	400	413	125	216	300
16	400	630	550	166	288	400
16	630	800	690	208	360	500
16	630	1000	830	249	431	600

مشمولات كاحبدول

سيكشن

- ڈیا کھولت اور حباقی پڑتال کرنا
- 2.1 تحفظ 2.1 يوزيشنگ 2.2 يوزيشنگ 2.2 نظام مواداري 2.3 نظام مواداري 2.3 تارين اور مسربوط کاريان 2.4 2.5 تارين اور مسربوط کاريان 2.5 تارين والے کنيشنز 2.6 تارين والے کنيشنز 2.6 حبانے والے کنيشنز 2.7
- . مستقم پاور آپ
- المسلی تعمیلات 4.1 4.1 عسوی نصوصیت AVR 4.2 خصوصیت AVR 4.3 خصوصیت AVR 4.4 خصوصیت HA 4.4 خصوصیت 4.5 بائی پاسس نصوصیت 4.6
- 18
- اذالہ متعمی کاری

 6.1

 6.2

 عناط ابت داء

 6.3

 شٹ ٹے ڈاؤن

 6.4

 نقعی موث

 6.5
- . خصوصیات

حبدول 2.4.1 میں ان یٹ اور آؤٹ پٹ بریمر کی تجویز کردہ ریٹنگز دی گئی ہیں۔ نے دی حبانے والی ویلیوز انٹ ریولیٹڈ ہو سکتی ہیں۔ اسس حقیقت کے باعث کہ بریکر کی ریٹنگز میں ایک بڑے پیانے پر اضاف ہوتا ہے یہ تجویز دی حباتی ہے کہ ٹریے کی تبابل تغیر سطح کے MCCBs استعال کے جبائیں۔ اسس طسرح اعسلی سطحی تحفظ حساصل کیا جبا سکتا ہے۔ ان پٹ MCCB اسس قتم کا ہونا حیا بیٹے جو (زائد ابت دائی سرج کرنٹ کے حامل) انڈکٹیو لوڈز کے ساتھ کام کرنے کے لیے مناسب ہو۔ آؤٹ پٹ بریکر کا انتخاب لوڈ کی نوعیت کی مناسب سے کیا جبانا حیاہیئے۔

آنے والے کنیکٹنز

آنے والی تینوں تاریں آنے والی نالیوں (INCOMING MAINS) کے طور پر نشان زد کردہ سیکشن میں موجود ٹرمینل پینل پر ان ٹرمینلز سے مسربوط ہونی حیابئیں جنہیں R1 S2 T3 کے نام سے نامسزد کیا گیا ہو۔ آنے والے نیوٹرل کو N ٹرمینل سے مسربوط کیا حیاتا ہے اور سسٹم ارتھ کو E ٹرمینل سے مسربوط کیا حباتا ہے۔ توجبہ مسٹرمائیں AVR کو ایک آنے والا نیوٹرل مسٹراہم کیا حبانا حیابیئے جس کی مکسل درجبہ بندی کی حبانی حیا بیئے۔ اسس امسر کو یقینی بنانے کے لیے دھیان رکھ حبانا حیا بیئے کہ تمام ٹرمینلز حضاظت کے ساتھ مفہوطی سے کے ہوئے ہوں۔ 2.6.1 ڈائیگرام ملاحظہ کریں

حبانے والی تعینوں تاریں حبانے والے مینز کے طور پر نشان زد کردہ سیکشن میں موجود ٹرمینل پینل پر ان ٹرمینلز سے مسربوط ہونی حیابئیں جنہیں R1 S2 T3 کے نام سے نامسزد کیا گیا ہو۔ حبانے والے نیوٹرل کو N ٹرمینل سے مسربوط کیا حبانا حیاہے اور لوڈ ارتھ کو E ٹرمینل سے مسربوط کیا حبانا حیاہے۔ N.B. نیوٹرلز کی مکسل درحبہ بندی کی حبانی حیابیئے۔ اسس امسر کو یقینی بنانے کے لیے دھیان رکھیا حبانا حیابیئے کہ تمام ٹرمینلز حضاظت کے ساتھ مفہوطی سے کے ہوئے ہوں۔ ڈائیگرام 2.6.1 ملاحظ۔ کریں ان پٹ سے آؤٹ پٹ تک فیز روٹیش

> آنے والے مینز R1 = فيز 1 إن S2 = فيز 2 إن T3 = فيز 3 إن N = مكسل طور ير درحب سند تده نيوٹرل إن E = ارتھ سسيلائي

حبانے والی مینز R1 = فيز 1 آؤك __ S2 = فيز 2 آؤك = S2 T3 = فيز 3 آؤك __ N = مکسل طور پر درجب سند تده نیوٹرل آؤٹ E = لوڈ ارتھ

کنیکٹنز چوڑی والے ٹرمینلز کا استعال کرتے ہوئے متائم کیے حبانے حیابئیں یا منسراہم کردہ پیجوں والے ٹرمینلز کا استعال کرتے ہوئے۔ یقینی بنائیں کہ گنیکشنز کیے ہوئے ہیں۔

3. نظام کی یاور آن کرنا

پہلی بار نظام کی یاور آن کرنے سے قبل صرف کی متند کارکن کی حبانب سے مندرج ذیل پر تالیں کی حبانی حیائیں۔

ان پٹ اور آؤٹ پٹ بڑسنیشنز کی مضبوطی، درست وائرنگ اور فیز روٹیشن کی پڑتال کریں۔


- 1. پڑتال کریں کہ عمارت کی برقی سروسس میں اتنی صلاحیت ہو کہ AVR کو ان پٹ کرنٹ منسراہم کیا جبا سے، اسس بات کو . مدنظ سرر کھتے ہوئے کہ یہ لوڈ کو منسراہم کردہ بیرونی کرنٹ سے 40٪ زائد ہو سکتا ہے۔
- 2. پڑتال کریں کہ عمارت کی برقی سروسس کی نامسزد وولٹیج (nominal voltage) اور وائزنگ کی ترتیب درست ہے اور یہ کہ مسرکزی سرکٹ بریکرز AVR کی حبانب سے پیش کردہ لوڈ کی استقرائی نوعیت کے لیے موزوں ہوں۔
- 3. کینی بن کمی کہ لوڈ کا سازوس مان توانائی پانے کے لیے تیار ہو۔ ایک بار مندر حب بالا شرائط کی تصدیق ہو حبائے تو AVR پر اِن پٹ پاور کا اطلاق کیا حب سکتا ہے۔ اِن پٹ پاور کے اطلاق کے بعد AVR کے دروازے پر لگے تین ڈیجیٹل وولٹیج میٹرز پر درست آؤٹ پٹ ولٹیج کی نشاندہی ہونی حب ہے۔ اگر ایسا نہیں ہوتا تو فوری طور پر پاور بند کریں اور اسس کتابج کے ازالہ نقص کاری کے سیکشن سے رجوع کریں۔ دروازے پر گے AVS نشان کاروں (اگر نصب شدہ ہیں) کو 'آن' ظہر کرنا حب ہے (3 منٹ کے انظار کے بعد)۔

اِن پٹ یاور کے اطسال کے بعبہ AVR کے دروازے پر لگے تین ڈیجیٹل وولٹیج میٹرز پر درست آؤٹ پٹ وولٹیج کی نشاندہی ہونی حیاہے۔ اگر ایسا نہیں ہوتا تو فوری طور پر یاور بنند کریں اور اسس کتابیج کے ازالہ نقص کاری کے سیکشن سے رجوع کریں۔ دروازے پر لگھ AVS نشان کاروں کو 'آن' ظاہر کرنا حیاہیے (3 منٹ کے انظار کے بعبد)۔ ایک بار اوپر تصدیق ہو حبانے کے بعبد کہ AVR درست انداز میں کام کر رہا ہے، آنے والی یاور آن کر دی حبانی ب بینے اور بیرونی سے کٹ بریمر کو آن کی حالت پر ترتیب دے دیا جبانا حیاہئے۔ اب اگر دوبارہ سے پاور کا اطلاق کیا جبائے، تو 3 منٹ کے انتظار کا وقت گزر حبانے کے بعب لوڈ کو خود کار طور پر منسراہم کر دیا حبائے گا۔

تھےری فیز AVR تین کیساں سنگل فیزریگولیٹر یونٹس سے مسل کر بن ہے۔ ان میں سے ہر ایک اپنے آؤٹ پٹ ووکٹیج کی نگرانی کرتا ہے اور نالیوں میں منسراہم کردہ وولئیج میں آنے والی تبدیلیوں کے مطبابق ایڈجسٹ ہو حباتا ہے تاکہ متسرین حسدود کے اندر آؤٹ پٹ وولئیج کو بر مترار رکھ جب سے۔ جب AVS خصوصیت کو نصب کیا حبائے تو ریگولیٹرز کے آؤٹ پٹ معتامات کو ایک ربط کار کے ذریعے لوڈ سے مسربوط کیا حباتا ہے۔ یہ ربط کار ایک خودکار تھسری فیز وولٹیج سوئج PCB کی حبانب سے حیالیا حباتا ہے جو کہ AVR آؤٹ پٹسس کی نگرانی کرتا ہے۔ یہ صرف اسس وقت ہی لوڈ کو مسربوط کرتا ہے جب فیز کے تمسام ووکٹیجز ت بل قسبول حدود کے اندر ہوں۔ اسس صورے میں اومتاہے میں تاخیر ہوتی ہے جب تمام وولٹیجز ایک مخصوص حسد کے اندر موصول ہوں اور ربط کار آن ہو۔ ایبا اسس لیے ہوتا ہے۔ تاکہ نالیوں کی سے لائی غیر معمولی طور پر بے ترتیب ہونے کی صورت میں سے لائی کو مستحکم کیا جب سے اور لوڈ کو بارہا آن اور آف ہونے سے روکا ب سے۔ AVS سرکٹ کی صور تحال کی نشاندہی تین بڑی LEDs کی حبانب سے سامنے والے بینل پر کی حباتی ہے، جن میں سبز کا مطلب آن، پیلی کا مطلب انتظار اور سسرخ کا مطلب آن ہے۔

یہ آؤٹ پٹ معتام پر ٹیپ کے ذریعے تبریلی کے حسامسل خود کار ٹرانسفار مسر پر مشتل ہوتی ہے۔ ہر ٹرانسفار مسر پر سات ٹیپی کی خصوصیت موجود ہوتی ہے جو کہ اِن یٹ وولٹیج کے ایک وسیع سلطے کے لیے مناسب آؤٹ یٹ وولٹیج منسراہم کرتے ہیں۔ موٹر کو حشروع کرنے کے لوڈز سے نمٹنے کے لیے یہ ٹیپن بہتر طور پر در حب سند Triac مینٹس کی حبانب سے سوچ کیے حباتے ہیں۔ کم معیاری مذمت کار (resistors) ہر Triac کے ساتھ نصب کے حباتے ہیں تاکہ اسس بات کو یقینی بنایا حبا سکے کہ ہر بینک کے اندر موجود Triacs کے مابین مساوی طور پر ہائی کرنٹس کا اشتراک کیا جب سے۔ اسس تکنیک کا نتیجہ ایک ایے وولٹیج کے اسٹیبلائزر کی صورت میں نکلت ہے جس کا کوئی بھی ھے۔ حسر کت نہیں کرتا، وولٹیج میں آنے والے اتار حپڑھاؤ پر فوری جوابی کارروائی کرتا ہے اور ریگولیشن کی مختلف تکانیک کا استعال کرنے والے دیگر AVRs جتنا بڑا یا تعب اری نہیں ہو تا۔

ایک مائیکرو گنٹ رولر اسس گنٹ رول سسٹم کا دل ہوتا ہے۔ یہ AVR کے آؤٹ پٹ وولٹیج کی پیاٹش کرتا ہے اور درست ٹیپ کے انتخناب کے لیے مناسب Triac بینک کو آن کرتا ہے۔ آؤٹ پٹ وولٹیج کی معقول ایڈجٹمنٹ کے لیے ایک پوٹینشیو میٹر فنسراہم کیا حباتا ہے۔ یہ مائیکرو گنٹ رولر نالیوں کی سپلائی کی منسر یکوئنسی کی پیاکٹس بھی کرتا ہے اور اسس کی منسبت سے کمی بیثی پوری کرتا ہے۔ اسس کا بیہ مطلب بھی ہے کہ AVR خود کار طور پر منسر یکوئنسی کی 45 سے 88Hz پر اور مختصبر دورانیوں کے لیے 30Hz تک کی کم حسد پر کام کرے گا تاکہ ڈیزل جنسریٹر کے لوڈنگ کے مسائل سے نمٹنے میں مدد سنسراہم کر سکے۔



ڈائیگرام 2.6.1 ٹرمینل کا ہندوبست

فن ریوئنسی اور وولٹیج کی پیائشیں سے کٹ اور سافٹ ویئر کی حبانب سے فلٹر کی حباق ہیں تاکہ شور کو ہٹایا حبا سے اور اسس طسرح دید میں آنے والی جعلی تبدیلیوں کو روکا حبا سے۔

مائیکرو کنٹ رولر میں ایک واج ڈاگ خصوصیت کا اطسال کیا حباتا ہے۔ یہ خود مخت ار طور پر مائیکرو کنٹ رولر اور اسس کے سافٹ ویئر کی عمسل کاری کی نگرانی کرتی ہے۔ اگر یہ کسی عضاط کام کی نشاندہی کرے، تو یہ مائیکرو کو دوبارہ سے ترتیب دے گی اور دوبارہ سے کنٹسرول نظام کا آغاز کرے گا۔

کنٹ رول سے کے دی جب نے والی کم وولٹیج پر مشتل DC سیلائی کی حن اظت بھی فیوز سے کی حباتی ہے۔

مسندید برآن، ہارڈ ویئر ری سیٹ سسرکٹ شامسل کیا جباتا ہے جو کہ گنشے رول سسرکٹ کی سیلائی ریل کی نگرانی کرتا ہے۔ اگر نالیاں اسس حالت پر واپس لے حبائے گا اور تمام Triacs کو آف کر دے گا۔

جب نالیوں کی سپلائی ت بل استعال حد تک بڑھ جائے، تو گران سرکٹ مائیکرو کو دوبارہ پلائے گا اور دوبارہ سے سٹم کا آغناز کیا حبائے گا۔ یہ براؤن آؤٹ یا بلیک آؤٹ کی حسالت سے ایک منظم اور کنٹرولڈ طسریقے سے دوبارہ چلت کیٹی بناتا ہے۔ یہ سسرکٹ ایک وسیع ہسٹرلیسیس کے ساتھ تیار کیا حباتا ہے تاکہ پونٹ اسس وقت تک دوبارہ سے آن ہونے کی کوشش نے کرے جب تک کہ سپائی وولٹیج یونٹ کے شروع ہونے پر وولٹیج کے مکنہ حپڑھاؤے نمٹنے کے لیے کافی نہ ہو۔ یہ کرنٹ میں اسس فتم کے ۔ حیارہاؤ کے امکان سے بحیاتی ہے جو کہ سیلائی کو اسس حد تک گرنے پر محببور کر دے کہ یونٹ دوبارہ سے آف ہو حبائے۔

ہر ٹرانسفار مسر کے ساتھ نصب در حب حسرارت کے سینسرز کی حبانب سے اصنافی تحفظ منسراہم کیا حباتا ہے۔ اگر AVR کو مکسل لوڈ کے ساتھ استعال کیا حیائے اور یا تو ماحولیاتی درجبہ حسرارت نہایت زیادہ ہو یا ہواداری کی حیالیاں بند ہوں، توٹرانسفار مسر کا در حب حسرارت معقول حدود ہے کہیں زیادہ بڑھ سکتا ہے۔ اسس قتم کی صور تحسال میں، در حب حسرارت کا سینسر سیلائی کو متعسلقہ کنٹ رول بورڈ سے غیر مسربوط کر دے گا اور نتیجتا آؤٹ پٹ معتام کو آن کر دے گا۔ ٹرانسفار مسر کے مناسب حسد تک ٹھنڈا ہو حانے کے بعد، سینسر AVR کو دوبارہ حیلائے گا۔

مندرجب بالا صور تحسال کے بعد دوبارہ حیلاتے ہوئے AVR احیانک ہی آلات کے کام کرنے کا سبب بن سکتا ہے۔ اسس امسر کو یقیٰ بنانے کے لیے احتدامات کے حبانے حیائیں کہ اسس سے نمی شخص کو کوئی خطرہ نہ ہو۔

AVS خصوصیت [افتیاری - حسریداری کے وقت علیحدہ سے آرڈر دیا حبانا حیا بینے] 4.3.1

آٹومیٹک وولٹیج سوئچ (AVS) برقی نالیوں کی سیلائی میں اتار حپڑھاؤ، مداحساتوں اور دیگر غیر معمولی سرگرمیوں کے مسلاف برقی آلات کے تحفظ کی ڈیوائٹس ہے۔

تھےری فیز AVS نالیوں کی سیلائی کے مختلف پیرامیٹرز کی نگرانی کرتا ہے اور اسے برزوں سے مسربوط رکھتا ہے بشرطیکہ تمسام پیرامیٹرز تعمین کردہ تابل تسبول حدود کے اندر ہوں۔ یہی عسام صور تحسال ہے اور اسس کی نشاندہی ایک سبز LED (لائٹ ایمیٹنگ ڈائیوڈ) کی حبانب سے کی حباتی ہے۔ اگر نالیوں کی وولٹیج ان حیدود کو یار کر حبائے، تو AVS سازوسامان کو نالیوں سے غیر مسربوط کر دیتا ہے اور اسس کی نشاندہی سرخ LED کی حبانب سے کی حباتی ہے (بعض صور تول میں، غیر مسربوط کیے بغیر ہی نشاندہی کا انتخاب مسکن ہے۔) نالیول کی سیلائی ت بل قسبول حدود میں واپس آنے کے بعد، جس کی نشاندہی زرد LED سے کی حباتی ہے، انظار کی مدی کے دوران نالیاں سازوسامان سے غیر مسربوط رہتی ہیں اور فیکٹری کی حبانب سے منتخب کردہ احبزاء کے مطابق نامسزد کردہ 1 منٹ پر ترتیب دی حباتی ہیں۔ اگر انتظار کے وقت کے دوران یہ نالیاں ایک بار پھسر سے حسدور یار کر حبائیں، تو ایک نئے سسرے سے انتظار کی مدے کا آغساز ہو گا۔ انظار کی مدے کے اختتام پر، جب نالیوں کی سیلائی اپنی مدے کے بیش نظسر مسلسل حدود کے اندر رہتی حیلی آ رہی ہو، تو یہ اپنی عسومی حسالت پر لوٹ آتی ہے جس کی نشاندہی سبز LED سے کی حباتی ہے اور سازوسامان کو دوبارہ سے نالیوں سے مسربوط کیا

تھےری فیز AVS کی زیر نگرانی خصوصی پیرامیٹرز یہ ہیں:

a) نالیوں کے وولٹیج کی تدر

عسومی صور تحسال وہ ہوتی ہے کہ جب تمسام فیزز کی نالیوں کے وولٹیج کی افتدار بیٹنگل سیٹ کردہ خصوصی حسدود کے اندر ہوں جنہیں "ونڈو" کہا گیا ہے۔ کی ایک یا زائد فیزز کے وولٹیج ونڈو سے باہر حبانے کی AVS نشاندہی کرتا ہے، حیاہے وولٹیج زائد ہو یا کم۔

b) فيز كا تعلق (ٹائمنگ)

AVS سیلائی کے تین فیزز کے مامین فیزیر مشتل تعلق کی نگرانی کرتا ہے۔ عصومی صور تحال وہ ہوتی ہے کہ جب T/3 کے مطابق، جہاں T ایک حیکر کی مدت ہو، تینول فیزز کے درمیان موجود منسرق 120 ڈگریز پر مشتمل ہو۔

AVS تھے ری فیز پر مشتل نالیوں کی سیلائی میں فیز رو ٹمیشن کے نقص کی نشاندہی کر سکتا ہے۔ مندر حب بالا c) اور d) بیرامیٹرز کی نشاندہی معاری نہیں، بلکہ ایک افتیاری بلگ ان بورڈ کے ذریعے ساصل کی حباتی ہیں۔ اسس بورڈ پر، ایک d.i.l.l سوچ کے ذریعے یہ انتخاب ممکن ہے کہ آیا کی غیر معمولی سے گرمی کی محض نشاندی کی گئی ہے یا یہ غیر مسربوط کرنے کا باعث بھی ہستی ہے۔

4.3.2 عمل کاری کا اصول

ف مین اور فیز روٹیش کی نشاندی کے سے کٹس کی تفصیلات ایک علیحدہ سیکشن میں بیان کی گئی ہیں۔ دیگر بیرامیٹرز کی نشاندی کے لیے AVS کی حبانب سے کیے حبانے والے تفصیلی عمسل کی وضاحت ذیل میں سسرکٹ کی تفصیات کے تحت کی گئی ہے۔ تاہم، بنیادی طور پر، AVS ہر فیز کے نالیوں کے AC سائینوسائڈ کی اعسلٰی ترین سطح کا موازے دو حوالہ حبات کے ساتھ کرتا ہے، جن میں سے ایک کا تعسل ونڈو کی کم سطحی یا کم وولٹیج کی حسد ہے ہے، جبکہ دوسے کا تعسلق بلنند سطحی یا زائد وولٹیج کی حسد سے ہے۔ اگر نالیاں عسمومی ہوں، اسس طسرت سے کہ یہ بلند ترین مطحیں دو حدود کے ساتھ ساتھ ایک ایسے وقت کے اندر واقع ہوں جو T/3 سے متحباوز ن ہو (T ایک حپکر کی مدت ہے)، تو ایک مونو اسٹیبل حسرکت یاتا ہے جو کہ انظار کی مدت کے بعید آلے کی یاور کو سوچ کرتا ہے۔ اگر ایک یا زائد بلند ترین سطحیں کم تر حید کے اندر ہوں، زائد حید سے اوپر ہوں یا دو متواتر بلند ترین سطحول کے در میان مناصلہ T/3 سے متحباوز ہو، تو سازوسامان کو غیر مسربوط کرنے کے لیے AVS کو ری سیٹ کیا حباتا ہے۔

4.3.3 يزتالين اور ايد جستمنش

a) ونڈو کی حسدود

P1 اور P2 تینوں فیرز کو یکیاں بنانے کے لیے ایڈ جسٹ کی حباتی ہیں، تاکہ P1 اسس پیک کو ایڈ جسٹ کر سکے جو P1 اور R12 کے در میان ہو، اور P2 اسس پیک کو ایڈ جسٹ کر سکے جو کہ P2 اور R20 کے در میان ہو تا کہ انہیں R2 اور R3 کے در میان موجود پیک کی بلند ترین سطح کے برابر لایا جبا سے۔ پیائٹس کے لیے، AC کی سطح پر ایک عسام ملٹی میٹر یا ڈیجیٹل ملٹی میٹر استعال کیا جبا سکتا ہے، چونکہ یہ ایسی پیائٹیں مسراہم کرتے ہیں جو کہ بلند ترین سطح سے مستناسب ہوں۔

P3 اور P4 ونڈو کی حدود کو ایڈجسٹ کرتے ہیں۔ ان کی گردسش کے مسرکز کے گرد و نواح سے آغناز کیجے۔ عصومی تھسری فیز سپلائی کو Variac کے ذریعے ایک فیزے AVS سے مسربوط کریں اور وولٹ میٹر کے ساتھ وولٹیج کی نگرانی کریں۔ Variac کو کم تر وولٹیج کی حسد پر ایڈ جسٹ کریں۔ P4 کو ایڈ جسٹ کریں تاکہ یہ نشاندہی سرخ سے زردمیں تبدیل ہو حبائے۔ Variac کو زائد وولٹیج کی حسد پر ایڈ جسٹ کریں۔ P3 کو ایڈجسٹ کریں تاکہ یہ نشاندہی زرد سے سرخ میں تبدیل ہو حبائے۔

اگر Variac کو اسس طسرت سے ترتیب دیا حبائے کہ وولٹیج ونڈو کے اندر ہی رہے، اور زرد روشنی نشاندہی کر رہی ہو، تو انظار کے وقت (نامسزد کردہ 1 منٹ) کے بعد سبز روسشنی نشاندہی کرے گی اور ربط کار کی توانائی بحال ہو حبائے گا۔

ایک مکسل پڑتال کے لیے، تین Variacs کا استعال کیا جبانا حیا ہے، جس میں ہر فیز کے لیے ایک کا استعال کیا حبائے، اور دیگر کے ساتھ ۔ کم تر اور زائد وولٹیج کے مخلف امتزاحبات کی پڑتال بھی کی حبائے۔

b) انتظار کا وقت

انتظار کا وقت 0.7xR37xC6 کے حالب سے دیا حباتا ہے۔ R37 = 820K اور C6 = 100uF کے ساتھ، انتظار کا وقت اندازاً 60 سیکنڈ سے لے کر احبزاء کی برداشت کی حسد کے اندر تک ہوتا ہے۔

یہ اختیار AVR (آٹومیٹک وولٹیج ریگولیز) کے 21kVA سے بڑے تھے ری فیرز پر مشتل یونٹس کی تمام درجبہ سندیوں پر دستیاب ہے۔

معاری تھے ری فیز AVR ایک ایسا آؤٹ پٹ معتام فنسراہم کرتا ہے جو کہ ایک وضع کردہ اندازے کے معتابلے میں اِن پٹ وولٹیج کے بر27 + پر مشتل منسرق کو مدنظ سر رکھتے ہوئے + 4٪ کے اندر مستحکم ہو۔ اگر حب اسس بات کا امکان ہے کہ وولٹیج کا + 4٪ استحکام زیادہ تر صارفین کی ضروریات پر اپورا ازے گا، تاہم معیاری AVR نظام سے پرے مسنید 'بہستر' ریزولیوسٹن پر مسبنی مسر کیے کو شامسل کرتے ہوئ اعسلیٰ معیاری در سستگی منسراہم کی حب سستی ہے۔

6. ازاله نقص کاری

6.1 شخا

یونٹ پر کی بھی صورت میں کام نہیں کیا حبانا حیا پئے بشرطیکر سیلائی کو الگ سنہ کیا حبائے۔

6.2 عناط ابتدا

اگریہ دیکھا حبائے کہ AVR آغناز کی کوشش کرتا رہتا ہے لیکن فوراً ہی بند ہو حباتا ہے، تو بہت حسد تک امکان ہے کہ ایسا AVR یا عمارت میں عناط وائزنگ کے باعث ہو۔ مسکن ہے کہ وحب یہ ہو:

- 1. تارین موٹی نہیں۔
- 2. موٹائی کے مصالح میں تارین اسس متدر لمبی ہیں کہ وولئ میں شدید کی کا باعث بستی ہیں۔
 - 3. حنراب جوڑ یا کنیکشنز۔

اسس قتم کے ہر مسئلے کا حسل کیا جبانا جباہیے، تاکہ سیلائی زائد کرنٹسس منسراہم کر سے جوکہ لوڈ چلانے کے لیے ضروری ہے۔

اگرید دیکھا حبائے کہ یونٹ کچھ دیر میں آف ہو حباتا ہے حیاہے نالیوں کا وولٹیج اچھا ہی کیوں نے ہو، تو ممکن ہے کہ AVS نالیوں کی سیلائی کی کئی بری صور تحسال کی نشاندہی کر رہا ہو جو کہ تعیث آلات کے استعال کے بغیر واضح نہیں ہو سکتی۔ متبادل طور پر، ممکن ہے کہ در حب حسرار میں اضافی لوڈ زیر عمسل ہو، جس کی صور میں مندر جب ذیل پہلوؤں کی پڑتال کی حبانی حیابیہ:

- 1. آؤٹ یٹ کرنٹ AVR کی عقبی حبانب لگے سریل لیبل میں واضح کردہ حمد سے زائد نہیں۔
- 2. AVR حسرارت کے ماخبذ کے پاکس ایک حضراب مصام کے باعث شدید مادولیاتی درجب حسرارت کا شکار نہیں۔
 - 3. AVR کیس کے اطسران میں گئی ہواداری کی حبالیاں ڈھکی یا مدود نہیں کی گئیں۔
 - 4. یہ کہ AVR کیس ورک کے بیرونی تھے کے ارد گرد ہوا کی آزادان قرور فت کے لیے جاکہ موجود ہو۔

6.4 ازالہ نقع کاری کے عصمومی نکات

مسئلہ سوچ آن کرنے پر AVR مین کے بریکر کو ٹرپ کر دیتا ہے	وہ اسل 1. پڑتال کریں کے ان پٹ اور آؤٹ پٹ وائرنگ مشارٹ نے ہو۔ 2. پڑتال کریں کہ اِن پٹ سسر کٹ بریکر استقرائی لوڈز کے لیے موزوں ہو۔
عسومی عمسل کے بعد AVR سند ہو حباتا ہے۔ مدود شدہ سنہ ہول۔	1. پڑتال کریں کہ لوڈ در حب بند آؤٹ پٹ سے متحباوز سنہ ہو۔
20% 20% 3350	2. پڑتال کریں کہ ہواداری نالیاں/ <u>سنکھ</u> کی تجبین 3. مسکن ہے کہ آنے والا وولٹیج AVR برقی سسٹمز کے حپلانے کے لیے بہت کم ہو۔
آن کے حبانے پر AVR فوری طور پر بند ہو حباتا ہے۔	 یر ٹال کریں کہ ٹرمینل کے جوڑ اور کنیکٹنز اظمینان کن انداز میں بنے ہوں۔ یر ٹال کریں کہ آنے والی تار من سب گنجب کشس کی حسام ہو۔ یر ٹال کریں کہ کہیں تار کی حسد سے زیادہ لمب آئی وولٹیج میں سشدید کی کا باعث بن رہی ہو۔
اِن پٹ پاور موجود ہے لیکن آؤٹ پٹ نہیں۔	1. پڑتال کریں کہ AVS کے نشان کاروں میں (اگر نصب مشدہ ہیں) 'آن' ظاہر ہو رہا ہو 2. پڑتال کریں کہ سرکٹ بریکرز (اگر نصب شدہ ہیں) 'آن' کی حسالت میں ہوں۔
تین مسراحسل پر مشتل فیز پچپسلی مبانب گردسش کرتا ہے	فیز رو عیشن کا مسئلہ۔ آنے اور حبانے والے نالیوں کی وائرنگ کی پڑتال کریں

ایک معیاری AVR مکسل طور پر برقی (مستخکم) + 4٪ پر ریگولیٹ کردہ آؤٹ پٹ معتام منسراہم کرتے ہوئے 7 ٹیپ پر مشتل تبدیلی کے نظام پر مشتل ہے۔ یہ HH- اختیار کو منسراہم کیا حباتا ہے - جو کہ ×2.0 + پر مشتمل آؤٹ پٹ استحکام حساسسل کرنے کے لیے، مسزید 7 ٹیپن کا استعال کرتا ہے، جو کہ ایک بار پھسر سے مکسل طور پر برقی ہوتا ہے۔

4.5 بائی پاسس کا اختیار

4.5.1 وستى بائى پاسس

یہ سپلائی کو براہ راست لوڈ تک بائی پاسس کرتے ہوئے، AVR کو سرکٹ سے باہر نکالنے کے لیے استعمال کیا حباتا ہے۔ اسے انحبام دینے کے لیے، ریلے یا برتی نظام کے بر عکس، ایک مکسل طور پر درحب بند، متناسب، مکنیکل سوٹج استعمال کیا حباتا ہے۔ یہ اسس امسر کو یقینی بناتا ہے کہ کسی حبزو کی ناکامی یا سپلائی میں مداخلت کے باعث AVR کی سپلائی کو دوبارہ سے مسربوط نہ کیا حبا سے۔ یہ بائضوص اسس وقت ضروری ہوتا ہے جب بائی یاسس مسرمت فعال کرنے کے لیے استعمال کیا حبائے۔

4.5.2 خود كار باكي پاكس

یہ سہولت AVR میں کی قتم کا مسئلہ ہونے کی صورت میں سیلائی کو براہ راست لوڈ تک بائی پاسس کرنے کے لیے کام کرتی ہے۔ اگر ثران المسر کی نشاندہی کریں کہ اصافی لوڈ، ہواداری کے حسراب نظام یا زیادہ درجب حسرارت کے مسئلہ AVR درجب حسرارت کے باعث گری بڑھ رہی ہے تو بائی پاسس کام کرتا ہے۔ ای طسرح، اگر مائیکرو پروسیسر یہ نشاندہی کرے کہ مسئلہ AVR کے اندر بیش آیا ہے، تو سیلائی لوڈ کو بائی پاسس کر دی حباتی ہے۔

4.6 سرج اريسك

4.6.1 خصوصت

یہ یونٹ اسس لیے تیار کیا گیا ہے تاکہ تیز ووالٹیج کی اسپائلس اور سر حسنرے AVR یا AVR کی حسانب موجودہ سازوسامان کو نقصان پہنچانے سے روکا حساسے۔ اسمانی بحسل، ذیلی اعشین پر لوڈ کی سومچنگ یا بھاری موٹر لوڈ کی سومچنگ عصوماً ان اضافوں کا باعث سنتی ہے۔

4.6.2 عمسل كارى

یہ یونٹ AVR کی حبانب سے آنے والی سپلائی کے ساتھ ہی مسربوط کیا حباتا ہے، جو کہ محسرک کا کردار ادا کرتا ہے۔ اگر یہ AVR میں ہی نصب ہو تو یہ عقبی حبانب کگے کسٹشن ٹرمینلز کے اوپر واقع ہو گا۔ فی فیز دو نشاند ہیاں منسراہم کی حباتی ہیں تاکہ تحفظ کی کم سطح کے بارے میں انتباہ دیا حبا سکے، اسس طسرح سے کہ سسرج اریسڑ تحفظ کے کھونے سے قبل تبدیل کیا حبا سکے۔ یہ یونٹ کثیر مسرحلہ MOV کے حضاظتی سسرکش پر مشتل ہے۔

المسرمت

یہ ایک مکسل طور پر ٹھوسس حالت کا حسامسل AVR ہے جس کا کوئی حصہ حسر کت نہیں کرتا اور لہلنذا اے کم سے کم مسرمت درکار ہے۔ آپ AVR کی دیکھ بوسال چھوڑ کر بھی کئی سالوں تک کی بھی مشکل ہے یاک سروسس کی توقع کر سکتے ہیں۔

کی هم کی مسرمت سے قبل آنے والی نالیوں کی سیلائی کو علیمدہ کریں۔

مسرمت کے نام پر محض یہ درکار ہے کہ کیس ورک کے باہر اور اندر جی گرد کو صاف کر دیا حبائے جو کہ مسکن ہے کہ سازوسامان کی آزادات ہواداری میں رکاوٹ کا باعث بن رہی ہو۔ اگر PCB پر گرد جی ہو تو اے بھی کی زم برشش کی مدد سے اضاط کے ساتھ ہٹایا حبانا حبا ہئے۔ یہ عقسل کا تقساض ہے کہ وقت اُ فوقت اُ تمام سازوسامان کے برق کشیکٹنز کے شخط اور تاروں کی حساست کی پڑتال کر لی حبائے۔ ایک بار بھسر یقینی بن کیں کہ کام کے آغن نے قبل یاور آف کر دی گئی ہے۔

اگر کسی وجب ہے AVR کو نقصان کہنچ، یا آپ کو کسی نقص کا ٹائب ہو، تو رہنمائی کے لیے اپنے مصریب ترین موجود Sollatek نمائندے یا Sollatek (UK) کمیٹلا مسرکزی دفت رے رابطہ کریں۔

Sollatek UK Limited

Sollatek (UK) Ltd. Sollatek House, Waterside Drive, Langley, Slough SL3 6EZ UK

+44 (1753) 214 500 ثيليفون: 214 sales@sollatek.com www.sollatek.com THREE PHASE AUTOMATIC VOLTAGE REGULATOR Issue: July 2021 تحسرى فيز آلوييئك وولنشيخ ريكوليئر اشناصت: جوالكي 2021

6.5 منقص مووز

اگر AVR بند ہو گیا ہے تو یونٹ کے اندر موجود PCBs میں LEDs کا مشاہدہ مسکن ہے۔ یہ دو مخلف نقص موڈز ڈسیلے کر سکتے ہیں۔

یہ عسل محض مشند کارکن کی حبائب سے بی انحبام دیا حبانا حبا بیئے۔

یونٹ کا مسرکزی دروازہ اسس وقت بھی کھلا ہو سکتا ہے جب سپلائی مسربوط ہو۔ پھسر PCBs کو دیکھنا ممسکن ہے۔ تین PCB گروپس میں سے ہر ایک کے ایک کسنارے پر کئی LEDs واضح ہیں۔ نقص کی مسندر حب ذیل دو نشان دہیوں میں سے ایک کا مشاہدہ کیا جب سکتا ہے۔ 1. ایک حبکری طسرز میں گروپ اسکین میں چوکور LEDs جو کہ بار بار اوپر سے نیچے کی حبانب حب رہی ہوتی ہیں۔ یہ اسس بات کی نشاندہی ہے کہ وولٹیج کی پیاکشش کے فیڈ بیک سسرکٹ میں کوئی نقص پیش آگیا ہے۔ مثورے کے لیے اپنے مشریب ترین Sollatk


نمسائندے یا Sollatek (UK) کے رابطہ کریں۔ 2. ایک ہی گروپ فلیش میں موجود کم وولٹیج کی سبز اور سرخ LEDs جسکنے لگتی ہیں۔ یہ اسس بات کی نشاندہی ہے کہ AVR کے نظام میں کوئی حسرانی بیش آئی ہے۔ ایک بار پھر، مشورے کے لیے Sollatek سے رابطہ کریں۔

ان نشاند ہیوں کا مشاہرہ کی ایک یا تمام تین PCB گروپس میں کیا جب سکتا ہے۔

7. خصوصات

مافل	: تھسری فیز آٹومیٹک وولٹیج ریگولیٹر
اِن پـــــ وولنيج	: ×30× 400V (ويگر وولنتيجز وستيا <u>ب</u> بين)
آؤٹ پٹ وواٹیج	$230/400V + -4^{2}(+-2.0^{2})$ with HA Option):
در سنتگی کا وقت	: 15 سیکنڈ کے اندر اندر
مسنريوننى كى حسد	88Hz t 45Hz:
ووالمتي كالتحظ	: كم ووللمج كا خود كار تحفظ
THD	< 0.25 ^{\gamma} :
زیادہ سے زیادہ ماعولیاتی در حب حسرارے	40 C:
اكوسظك نوائز	< 45 dB:
سروسس کی متوقع مدت	> 25 :
فيكنالوجي	: مكسل طور پر ٹھوسس حسالت (مستحکم) موئچنگ
بائی پاسس مواز	: مسرمت کے لیے دستی بائی پاسس خود کار بائی پاسس آن
	(اختیاری) AVR کا نتقص اور اضافی لوژ-
رى اسسٹارے موؤز	: آؤٹ پٹ معتامتک سپلائی اسس صورت میں خود کار طور پر غیر مسربوط ہو حباتی ہے جب
	(اختیاری AVS) سیلائی پہلے سے وضع کردہ حدود کو پار کر حبائے اور اسس وقت دوبارہ مسربوط ہو
	حب تی ہے جب وولٹیج اچھا ہو۔ بلٹ ان 3 منٹ کی تاخیر۔
فلنسرنگ (اختیاری)	: اِن پیٹاور آؤٹ پیٹ شور مشرالے اور بڑھاؤ فلٹ ر شدہ ہیں ک
معارات	: مندر حب ذیل کیتمیل کے لیے تیار کردہ :-
	EN60065
	EN60555
	BSEN50081
	BSEN50082

APPENDIX 1: General Arrangement



Model	Weight	Dims (mm)
	kg	$W \times D \times H$
AVR3x20-22	100	450 x 635 x 850
AVR3x30-22	150	450 x 635 x 850
AVR3x50-22	210	500 x 685 x 1060
AVR3x75-22	285	600 x 735 x 1110
AVR3x100-22	400	500 x 835 x 1280
AVR3x150-22	450	500 x 835 x 1280
AVR3x200-22	575	680 x 1200 x 2070
AVR3x250-22	675	680 x 1200 x 2070
AVR3x300-22	735	680 x 1200 x 2070
AVR3x400-22	790	680 x 1200 x 2070
AVR3x700-22	1200	1360 x 1200 x 2070
AVR3x800-22	1590	1360 x 1200x 2070
AVR3x900-22	1700	1360 x1200 x 2070
AVR3x1000-22	1850	2040 x1200 x 2070

Up to 3000A per phase available

20 — jan

APPENDIX 2

Bypass installation procedure

1. Positioning

The bypass should be installed directly next to the AVR to allow wiring between the two units. Both units should be positioned as closely as possible to the incoming supply access. See AVR manual for further positioning requirements.




Fig 1. Bypass positioned close to AVR and utility access point

2. Interconnection

In the standard bypass connection configuration, the main incoming supply and load output are connected at the bypass. Connections are then made to and from the AVR using the terminals provided on the bypass terminal panel. The AVR and bypass should be connected together using the cable kit provided. This kit consists of nine identical cables two meters in length (three phases and neutral in and out plus one earth connection). The bypass terminal panel shows connection information. See AVR manual for further information on cable connection. **NB Ensure all connections are tight.**

The bypass is fitted with a terminal cover to prevent accidental contact with the terminals. It is necessary to remove this cover and feed the cables through before replacing it after the connections have been made.

3. Bypass operation

When the AVR is required to be in circuit, during normal operation, the operation handle on the top of the bypass case should be in the 'normal' position. This takes the incoming supply via the AVR to the load. When the AVR needs to be taken out of circuit, for instance to perform maintenance, the operation handle should be moved to the 'bypass' position. This takes the incoming mains directly to the load and the AVR is isolated.

4. Alternative bypass connection

There is an alternative bypass/AVR connection method that may be employed if desired. In this case, the bypass is used to select between the regulated supply from the AVR and the incoming mains supply as the feed to the load. Connections are as indicated on the terminal panel with the exception the terminals marked 'TO AVR' are not used. (See Diagram)





Fig 2. Bypass terminal panel marking


N.B. This arrangement does not allow the bypass to be used to isolate the AVR for maintenance.




APPENDIX 3


System topology diagrams


- 1. Main AVR
- 2. Main power PCBs
- 3. Cooling fans
- 4. LCD Display
- 5. Distribution surge protection
- 6. Fuse PCB
- 7. Automatic Voltage Switcher








Page 26











Final Test Procedure

Product Name: Installed Large AVR Variants: All ST165 based

Inspection Checklist

Document Number: QP07

- 1. Check PCBs for damage, poor alignment, comb positioning and general condition.
- 2. Ensure that all internal nuts, bolts and fixings are secure and that nothing has come loose during installation.
- 3. Examine all wiring, paying particular attention to power cable terminal tightness. If Bypass is fitted, check all power connections. Check crimp joints have not loosened.
 - Check all pink/grey connections are correct and that ribbon cable connectors have not been dislodged.
- 4. Clean all exterior panel work and check for damage.

Function Test

- 1. Note all results on form QF07.
- 2. Using a variac on input of one phase at a time, with a test lamp at the output, increase voltage until ST165 master switches on (reset LED goes off). Note input voltage. This should be in the range 140V to 170V.
- 3. Reduce input voltage and note voltage at which reset LED lights. This should be between 120V and 135V.
- 4. Increase input voltage from 160V and note output voltage at which tap down occurs on each tap. This should be at 240V +/- 1V.
- 5. From 270V reduce input voltage and note output voltage at which tap up occurs on each tap. This should be at 220V +/- 1V.
- 6. Set output voltage to 220V on brown tap. Input voltage should be less than 161V.
- 7. Set output voltage to 240V on violet tap. Input voltage should be greater than 280V.
- 8. Set input voltage to 230V. Compare measured input voltage to displayed input voltage. Difference should not exceed 2%.
- 9. Compare measured output voltage to displayed output voltage. Difference should not exceed 2%. AVS must be operational for this test.
- 10. Compare measured output current to displayed output current. Difference should not exceed +/- 10% at 20% full load. AVS must be operational for this test.
- 11. Connect two phases to the input of the AVR. Connect the third phase via the variac. Adjust the variac voltage to 230V. Time the delay before AVS switches on. This should 10 seconds +/- 5%. Ensure AVS amber LED illuminates during wait.
- 12. Increase variac voltage until AVS cuts out. Note AVS input voltage. This should be 260V +/- 3 V. Ensure Red overvoltage LED is illuminated.
- 13. Reduce input voltage to 230V. Ensure AVS amber LED is illuminated. Once AVS has re-connected reduce input voltage until AVS cuts out. Note AVS input voltage. This should be 190V +/- 3 V. Ensure red undervoltage LED is illuminated.
- 14. Note AVS HVD, LVD and Time delay settings.

Inspection and Test

Document Number: QF0

Product Name: Installed Large AVR Variants: All ST165 based

	Ins	pection Checklist		
1. PCBs				
2. Assembly				
3. Wiring4. Exterior				
4. Exterior		Function Test		
Tick for pass and enter value				
	R1 (value)	S2 (value)	T3 (value)	Limit
Switch on voltage		□		140V - 170V
Switch off voltage				120V - 135V
Tap down voltage				240+/-1V
Tap up voltage				220+/-1V
I/P V @ 220V out (brown)				< 161V
I/P V @ 240V out (violet)				> 280V
I/P V meter % acc.				+/- 2%
O/P V meter % acc.				+/- 2%
Current meter % acc.				+/- 10%
AVS Switch on time				3 min +/- 5%
AVS HVD operates				190V +/- 3V
AVS LVD operates				260V +/- 3V
AVS LED function				
AVS HVD setting				
AVS LVD setting				
AVS delay setting				
Inspected by (SUKL Engineer)	-			
Accepted by (Facilities Engineer)				
Date				

AVR on-site repair guide

Power PCB replacement procedure (Single PCB per Stack)

Ensure the AVR is isolated from the supply and load before commencing


- 1. Remove neutral sense cable (Single cable connected to J5)
- 2. Remove ribbon cable (connected to J2) if fitted.
- 3. Remove Pink/Grey cables (twisted pair to J6)
- 4. The PCB is fixed to the metalwork by means of 7 screws into nylon pillars. Removing these gives access to the back of the PCB.
- 5. Undo the 8 nuts/bolts securing the transformer connections to the rear of the PCB. NB the order in which these cables are connected should be noted for replacement. The Correct cable colour connections are marked on the PCB.
- 6. Remove faulty PCB. Ensure that the replacement PCB is exactly the same type as the removed PCB ie slave, master, 3 way, 5 way etc.
- 7. Fitting replacement PCB is a reversal of the above procedure.
- 8. It is essential that the On Site AVR Test Procedure following Maintenance/Repair for replaced power PCBs is followed before the AVR is put back on-line.

Power PCB replacement procedure (Multiple PCBs per Stack - see Photo)

Ensure the AVR is isolated from the supply and load before commencing

- 1. Remove front PCB neutral sense cable (Single cable connected to J5)
- 2. Remove front PCB ribbon cable (connected to J2)
- 3. Remove Pink/Grey cables (twisted pair to J6)
- 4. The front PCB is fixed to those behind by hexagonal brass pillars and nuts. To remove the the front PCB remove these nuts.
- 5. The same procedure should be repeated until the faulty board is outermost.
- 6. Replace faulty PCB. If this is the PCB with the transformer cables attached then the above procedure for single PCB per stack should be followed here. Ensure that the replacement PCB is exactly the same type as the removed PCB ie slave, master, 3 way, 5 way etc.
- 7. Re-assembling the PCB stack is the reverse of this procedure.
- 8. It is essential that the On Site AVR Test Procedure following Maintenance/Repair for replaced power PCBs is followed before the AVR is put back on-line.

In the large AVRs the main circuit boards are type ST165. There is one master PCB per phase and several slaves. In the picture below of an AVR3x400, there is one master and 7 slave PCBs.



Notes.

- 1. The Pink/grey wire brings low voltage ac from a small winding on the main transformer to power the circuit boards. It connects first to one PCB, and then links to all the rest.
- 2. The ribbon cable takes the control signals from the maser PCB and links it to all the slave PCBs.
- 3. There are seven round input LEDs on each PCB. These should all be on the same position for the PCBs on any one phase.
- 4. The Reset LED will only be on when the mains power is too low to operate the circuit boards correctly.

5. DSP replacement procedure

Ensure the AVR is isolated from the supply and load before commencing

- 1. Remove AVR back panel by undoing securing screws.
- 2. Remove cable access cover by undoing securing screws. The screws are covered by plastic inserts which must be removed.
- 3. Remove cables from terminals, noting cable order.
- 4. Pull cables out of DSP case.
- 5. Remove DSP from AVR by undoing two securing screws in cable access area.
- 6. Lift DSP off rear of AVR.
- 7. To fit new DSP, reverse the above procedure.
- 8. Test according to instructions in AVR Site Test Procedure
- 9. Replace back panel

Meter PCB replacement procedure

Ensure the AVR is isolated from the supply and load before commencing

- 1. Undo fixing nuts on rear of faulty meter PCB.
- 2. Remove PCB gently and disconnect ribbon connector.
- 3. Fit ribbon connector on replacement PCB.
- 4. Set replacement PCB in place on studs and replace nuts.
- 5. Ensure jumper on rear of PCB is set to the same setting as the removed PCB.
- 6. Test according to instructions in AVR Site Test Procedure.
- 7. If new meter PCB is out of adjustment, it can be re-calibrated using P1 on rear of replaced PCB. P1 should be adjusted until displayed voltage agrees with measured voltage.

AVS PCB replacement procedure

Ensure the AVR is isolated from the supply and load before commencing

- 1. On certain AVR models it will be necessary to remove the rear panel to access the AVS PCB.
- 2. Note all wiring colours and positions and AVS settings.
- 3. Remove all wiring.
- 4. Remove PCB by undoing screws
- 5. Place replacement PCB in position and fix.
- 6. Replace wiring in the same order as previously connected.
- 7. Ensure all voltage and delay setting knobs are set to the same positions as they were on the old PCB.
- 8. Test according to instructions in AVR Site Test Procedure
- 9. Replace back panel

AVS Contactor replacement procedure

Ensure the AVR is isolated from the supply and load before commencing

- 1. Remove AVR back panel by undoing securing screws.
- 2. Note all wiring positions.
- 3. Remove all wiring.
- 4. Undo securing bolts carefully. Larger contactors are heavy!
- 5. Remove old contactor and fix replacement in position.
- 6. Replace all wiring in the same order as previously connected.
- 7. Test according to instructions in AVR Site Test Procedure
- 8. Replace back panel

On Site AVR Test procedures following maintenance/repair

Items Required:

Single Phase Variac (Variable Transformer)

Multimeters

Clamp-on Current Meter

Test lamp

'Safebloc' Safety Mains Connector

Following Master PCB Replacement

The AVR should be disconnected from Mains and Load before commencing this test.

- 1. Connect the Variac input to a mains supply but do not switch on.
- 2. Connect Test Lamp across Neutral and output of phase under test.
- 3. Connect the Variac Neutral to the AVR incoming Neutral terminal
- 4. Connect Variac Live output to the Incoming Mains connection of the phase under Test.
- 5. UNITS WITH AVS ONLY Using Safebloc, connect (but do not switch on) mains supply live to terminal marked 'Test Use Only', situated bottom right of the rear panel. This will supply power to operate the AVS contactor, switching on the lamp at the output.
- 6. Reduce Variac output voltage setting to zero.
- 7. Connect Multimeter # 1 (indicating AC Voltage 600V scale) across variac output.
- 8. Connect Multimeter # 2 (indicating DC 20V scale) between TP1 (0V), and TP2 (5V).
- 9. Fit clamp-on current meter around variac live out cable (set to 200A)
- 10. Switch on power to variac and increase output voltage slowly observing current measurement.
- 11. Current should rise slowly and be no more than a few amps at 100V input.
- 12. Switch on supply to AVS Test Terminal. A loud thump will be heard as the contactor pulls in.
- 13. Set Master PCB Potentiometer P2 fully anti clock wise. Increase variac and check that TP2 reaches about 4.8V and stabilises when the mains reaches about 120V. Reset LED LD8 should be on, as should the green output LED LD13, but no others. Adjust P2 for 5.00Vdc.
- 14. Move meter positive lead to TP4 (7V). Check this stabilises between 6.8V and 7.2V when the variac is increased to 140V.
- 15. Continue to increase the variac and the Reset LED (LD8) should go off at approx. 140 to 150V mains in. The green tap LED (LD5) should come on and then move to the end (LD1). Check the lamp on the output comes on.
- 16. Turn P1 fully clockwise (indicates 240V). Turn the variac to 160V in). Check the output is between 210 and 230V ac and that the end red LED (LD1) is on.
- 17. Increase the variac until the AVR output is 241Vac +/- 0.5V. SLOWLY turn P1 anticlockwise until the output voltage drops (to approx. 222V). LED LD2 should now be on.
- 18. Reduce the variac until LD1 comes back on. SLOWLY increase the variac and check that the AVR output reaches 239 to 241V before dropping. (If not repeat steps 16 and 17 above). Keep increasing the variac and check that the voltage rises and drops in the same way a further 5 times. The round LEDs should move step

at a time to the end. Check P1 points to 230V on the PCB ident, +/-5V.

- 19. Slowly reduce the variac and check the output voltage goes down to 220V before rising again. This should happen a total of 6 times.
- 20. Increase and decrease the variac several times and check that all LEDs (LD1 to 7) light in turn. Check also that there is no 'thudding' noise made by either the transformer or the variac. (A faint 'click' may be heard from the PCB but this is normal.)
- 21. Switch the variac off and remove the neutral connection from J5 on the ST165. Turn the variac on again and check that the output lamp and green LED (LD5) come on for about 1 second and then go off, followed by the four rectangular LEDs lighting in a scanning pattern.
- 22. Switch off, reconnect the neutral and switch on. Check the output lamp comes on again.
- 23. Reduce the variac and check the output switches off at 130 to 135 V input.
- 24. Switch off and disconnect all mains power
- 25. Repeat the above procedure for the other phases if required.
- 26. The AVR is now ready for re-connection on-line.

Following Slave PCB Replacement

The AVR should be disconnected from Mains and Load before commencing this test.

- 1. Connect the Variac input to a mains supply but do not switch on.
- 2. Connect Test Lamp across Neutral and output of phase under test.
- 3. Connect the Variac Neutral to the AVR incoming Neutral terminal
- 4. Connect Variac Live output to the Incoming Mains connection of the phase under Test.
- 5. UNITS WITH AVS ONLY Using Safebloc, connect (but do not switch on) mains supply live to terminal marked 'Test Use Only', situated bottom right of the rear panel. This will supply power to operate the AVS contactor, switching on the lamp at the output.
- 6. Reduce Variac output voltage setting to zero.
- 7. Connect Multimeter #1 (indicating AC Voltage 600V scale) across variac output.
- 8. Fit clamp-on current meter around variac live out cable (set to 200A)
- 9. Vary input volts between 160 and 280V a number of times to ensure the replaced PCB is functioning properly. Lamp on output should be lit.
- 10. Leave on soak test for 1 hour.
- 11. Switch off and disconnect all input and output connections.
- 12. The AVR is now ready for re-connection on-line

Digital Meter Function Check

The AVR should be disconnected from Mains and Load before commencing this test.

- 1. Connect Variac as in PCB test procedure above.
- Connect Multimeter #1 to variac output
- 3. Connect Multimeter #2 to AVR output

- 4. Increase input volts to 170V.
- 5. Digital meter should indicate 170V when set to Input Volts using push-button.
- 6. Digital meter should indicate 234V when set to Output Volts using push-button.
- 7. Repeat for other phases.
- 8. Output current display can only be checked when AVR connected on-line in use with the load connected. Current displayed can be checked against actual output current measured using clamp-on current meter.

Distribution Surge Protection (DSP) function check

The AVR should be disconnected from Mains and Load before commencing this test.


- 1. Connect Variac as in PCB test procedure above.
- 2. Increase input volts to 230V.
- 3. Two LEDs on selected phase of DSP should be illuminated. The DSP is situated at the rear of the AVR. It may be necessary to remove the back panel to access the DSP.
- 4. If only one or no LEDs are illuminated, it means the protection on the selected phase is at a reduced level or completely ineffective, respectively. In either case the DSP should be replaced. See DSP replacement procedure.
- 5. Repeat for other phases.


Automatic Voltage Switcher (AVS) function check


The AVR should be disconnected from Mains and Load before commencing this test.


NB This is a complicated procedure and should only be attempted by a qualified electrician


- 1. Connect two incoming phases of the mains supply in the normal way.
- 2. Connect a variac to a mains supply, running from the third phase.
- 3. Connect a light bulb to the output of any phase.
- 4. Switch on the first two phases. The red LED on the AVS should be lit.
- 5. Set the variac to 230V and switch on.
- 6. Time the delay before the AVS switches on (the light bulb lights). This is the time delay, which can be adjusted on the AVS PCB using the DELAY pot. The green LED should be on.
- 7. Increase variac voltage until the AVS cuts out. The red high voltage LED should be on. The voltage at the input to the AVS should be around 260V. This can be adjusted on the AVS PCB using the HIGH V pot.
- 8. Decrease the variac voltage to 230V. The high amber LED should be on. Wait until the AVS switches back on.
- 9. Further decrease the variac voltage until the AVS cuts out again. The voltage at the input to the AVS should be around 190V. This can be adjusted on the AVS PCB using the LOW V pot.
- 10. Increase the variac voltage to 230V. The low amber LED should be on.
- 11. After the wait time the AVS should reconnect.
- 12. This concludes the AVS test.

























SOLLATEK UK LTD.

Tel: +44 (1753) 214 500 sales@sollatek.com www.sollatek.com

Sollatek (UK) Ltd. Sollatek House, Waterside Drive, Langley, Slough SL3 6EZ UK

ISO9001: 2015 accredited company

All weights and dimensions are approximate. Specifications are subject to change without prior notice. @Sollatek (UK) Limited 2021. All Rights Reserved. SQLLATEK and the SQLLATEK device are the trade marks of the Sollatek group of companies.